

Update Bulletin 2.10.5.2

#### Hello

Many updates of the past have been requested by various users and have finally made their way to your runtime version. A brief summary of the highlights are shown below.

Admin	.2
MathStuff	.2
Takeoff	.3
Detail pane	.3
Status Bar	.3
Location Status	.3
Item Replace	.5
Mullti-Edit	.6
Plan Lock	.7
Summary	.7
PlanExplorer	.8
PlanViewer	.9
Hyperlinks	.9
PinViewer	4
PlanRoom	5
Fix Captions1	5
Reports1	7
Svstem1	8
Graphics1	8
Backups	8
Missing Projects	9



# Admin

PinViewer link added to Material Spec page. Both images are combined as one.

😢 Edit Mater	al	2 🛛
Blum 125 deg	slip on	Material: \$2.25/Each [\$2.25/Each] Labor : \$0.00/Each [\$0.00/Each]
Material	Composites Labo	or Spec
Clip import Suppli	er Hemsely Distributors	tege mode up of higge orm (1) higge up of the ge mode up of higge orm, plue linge plote (3)
a. Au	Hemsely Distributors Atte	and reason for the survey of the second second

# MathStuff

Editing names where many expression are affected results in a progress bar.

Qty_cha Name: Qty_coa	Qty_elbow_catches_aw
Qty_dus Description:	Elbow catch at pr locked drs
- Qty_elbo - Qty_Enc Export:	
Qty_Exti	Zero_to_35
- Qty_fixe	
- Qty_hor:	
- Qty_non - Qty_hon	Save Cancel Help
Qty_hor	
Qty_intermediate_gbl	11
- Qty_invisible_seams	12
	12



## Takeoff

## Detail pane

**Includes Sell Amount** 

MATERIAL LABOR <b>COST</b>	= \$86.23 = \$327.41 = <b>\$413.64</b>	
SELL	= \$423.98	
SIZE	= 30.00[W] x 28.75[H] x 2	4.00[D]
ptions		
How many finish	ned ends	= 0
How many shell	ves adjustable	= Def_shelf_base
How many shell	ves fixed	= 0
How many shell	ves roll-out	= 0
How much extra	a shop labor (hr)	= 0.0
Is this item lock.	able = No	
What is the side	e extension @FE	= 00

### Status Bar

Status bar(pane 1) has been made wider and include 4 levels of location path. Paths which are too wide to fit are truncated from the middle as ".."

LOCATION 009- Southern Millwork \_Cabinetry\ F - Kitchen Rm 155\ Elev West 1 Line Items.

### **Location Status**

Button *Status Edit* has been moved back to the top toolbar to make room for button Plan Explorer. All buttons on toolbar now relate to node items.





Tagging locations with similar names has been added to Status editor.

Example: Tag all Mini Bars.





### Item Replace

Takeoff line items may now be *Replaced* with other items within the same library instead of first *Deleting* then *Adding* again.

/	Qty	Units	Product		Width	Height	Depth	Finish `
<u>ک</u> لا	2	Each	102 2 Door		34	34.5	24	PT-03
30 📯	1	Each	3/4" ACX Sub-T	ор	68	0	24	Doug Fir
) 🖬	1	Each	101 1 Door		24	34.5	24	PT-03
2	1	Each	3/4" ACX Sub-T			0	24	Doug Fir
5 🖬	2	Each	101 1 Door	Add	Ins	34.5	24	PT-03 4
4	1	Each	3/4" ACX Sub-T	Edit	F2	0	24	Doug Fir
5.1	1	Each	102 2 Door	Delete	e Del	34.5	24	PT-03
6	1	Each	3/4" ACX Sub-T	Repla	ce with	0	24	Doug Fir
1 🗖	1	Each	102 2 Door		and a second second	34.5	24	PT-03 🃢
8. 2	1	Each	3/4" ACX Sub-T	Clo <u>n</u> e		0	24	Doug Fir
9	_ 1	Each	101 1 Door	Copies	1	34.5	24	PT-03,-
	1.1	Each	3/4" ACX SIG.I	and have		A		Rour

Example - Replace with a Metal clad top from the same Countertop library. All properties will be preserved except for options.

Replac	e Tops_Vanites\3/4"ACX Sub-Top	REX
With	Buyout\ Metal clad	
🖃 Top	os & Vanites	
<u>ب</u>	B.O FSC Core LP Tops	
-	Buyout	
	- ADA Stone Lav Top w/Splash	
	Butcher block	
	- Cove top	
	- Cove top bar	
	E poxy top	
	Metal clad	
	Collinge	
	Solid autoop	
	Stone Credenza Top w/Splash	
÷.	Foveton	
÷.	Custom	
	Fin WD Tops/Ledges	
÷.	Self edge	
±	Solid Surface Tops	
	Stainles Steel Tops	
<b>±</b>	Vanities-Lav Tops	
Warn	ing - option values will be reset.	



#### Recalc item when done.

7	Qty	Units	Product	Width	Height	Depth	Finish
79 🖸	1	2 Each	102 2 Door	34	34.5	24	PT-03
-5080 😭		1 Each	3/4" ACX Sub-Top	68	0	24	Doug Fir
5081 🚺	1	1 Each	101 1 Door	24	34.5	24	PT-03
5082 🤜		1 Linft.	Metal clad	24	0	24	Doug Fir
483 🖸		2 Each	101 1 Door	27	34.5	24	PT-03
84.		1 Each	3/4" ACX Sub-Top	55	0	24	Doug Fir
-	1 mars	1 mch.	1 Provide and the second se	and a start	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	4	Phone Musical

### Mullti-Edit

Options may now be edited during a Multi-Edit selection. Common options will be identified and shown on the *Options* page. {a maximum of 500 line items are allowed for option editing.}

Qty	Units	Product		Width	Height	Depth	Finish
<u>ت</u>	2 Each	102 2 Door	1	34	34.5	24	PT-03
4	1 Each	3/4" ACX Sub-Top		68	0	24	Doug Fir 🧃
1	1 Each	101 1 Door		24	34.5	24	PT-03
7	1 Linft.	Metal clad		24	0	24	Doug Fir
11	2 Each	101 1 Door	13	27	34.5	24	PT-03
4	1 Each	3/4" ACX Sub-To	Add	Ins	0	24	Doug Fir
<u> 4</u>	1 Each	102 2 Door	Edit	F2	34.5	24	PT-03
4	1 Each	3/4" ACX Sub-To	Delet	e De	0	24	Doug Fir
<u>A</u>	1 Each	102 2 Door	Denla	ce with	34.5	24	PT-03
1 con	1 Each	3/4" ACX Sub-To	- Kepia	www.	0	24	Roug-Eir

General	Options	Costs	Sell	Tracker		
Category	D	escription			Choice	
Category1	H	ow many finishe	d ends			
	He	ow many shelve	s adjustable		0	
	H	ow many shelve	s fixed			
	H	ow many shelve	s roll-out			
	H	ow much extra s	hop labor (hr)			
	ls	this item lockab	le		Yes	~
	W	hat is the side e	xtension @FE			

No common option case:





## Plan Lock

Plan Lock/Unlock has been reworked to ensure that between project changes the lock setting is reset to the current Preference of "Plans Showing" (or not). (Similar attention has been given to button "*Show sub-locations*")



### Summary

Summary page includes sum by Product library.

Qty	UOM	Product		Material	Labor
9452.00	Linft.	02 - Base B/O 8" B/	0 Primed	\$27,883.40	\$69,306.79
18562.00	Linft.	05 - Casing B/O		\$26,205.18	\$119,075.23
2504.00	Linft.	06 - Casing B/O	<ul> <li>Product</li> </ul>	\$3,593.98	\$16,063.16
1020.00	Linft.	06.1 - Casing 3/4 x 2	Product Lib	rary \$1,275.00	\$6,543.30
1.00	Each	100 Open	Location	\$79.64	\$687.08
29.00	Each	101 1 Door	WorkOrder	\$2,480.76	\$9,081.59
15.00	Each	102 2 Door	Devision	\$1,874.21	\$5,362.96
2.00	Each	152 Sink 2 Door	Revision	\$237.98	\$922.65
1282.00	Linft.	19 - Trim at Ceiling B	/0	\$3,856.26	\$11,955.78
1.00	Each	2 Door - 30BC - H30		\$86.23	\$327.41
2.00	Each	2 Dwr Bunker		\$174.86	\$721.78
59443.00	Linft.	20 - Special Mldg 1		\$125,879.29	\$399,740.67
1.00	Each	233 3 File		\$137.89	\$405.28
2.00	Each	240 4 Wide drw		\$305.35	\$856.92
2.00	Each	254 4 Drw		\$194.14	\$805.32
1.00	Each	3 Dwr Unit		\$174.10	\$443.27
32.00	Each	3/4" ACX Sub-Top		\$497.28	\$4,577.63
10.00	Each	301 1 Door		\$891.62	\$3,013.37
14.00	Each	302 2 Door		\$1,837.90	\$4,603.22
3.00	Each	324 2 Door S&R gla:	35	\$1,036.74	\$1,691.40
166.00	Linft.	4/4 S4S To Make P	rofile	\$728.82	\$1,647.45
	Frahaman	Francisco La	here and a second second	AL.053	we go and the second se

Qty	UOM	Product Library	Material	Labor
1.0	00	Cab FSC	\$86.23	\$327.41
133.0	)0	Cab WIC	\$10,551.21	\$33,602.23
376.0	)0	Casino-Hospitality	\$37,312.33	\$114,015.44
99593.0	)0	Lumber	\$246,226.72	\$736,878.89
288.0	)0	Manufacturing	\$0.00	\$5,760.00
188.0	)0	Millwork	\$1,845.87	\$10,693.99
1590.0	00	Specialty Items	\$5,100.99	\$28,079.40
33.0	00	Tops & Vanites	\$508.23	\$4,634.60
5780.0	00	_Gen Con	\$44,951.61	\$84,016.00
A AMAGE AN	. Ann	A second second	A my prime	A. A. marine & Strating

People Logic Software Corp. Phone: 250.475.1392 Fax: 250.475.0792 info@peoplelogicsoftware.com www.peoplelogicsoftware.com



### PlanExplorer

A new concept is the ability to navigate to takeoff items using the viewports attached to drawings per location. Thus, the reverse of traversing from the location outline to items and drawings.

Plan Explorer is launched from a new button on the bottom of the location outline.



This dialog may remain open on another monitor as an Explorer and is even allowed to float over takeoff. All plans are shown along with the viewports(red) per page. By hovering around a viewport it will become selected in yellow and its corresponding location may be found by clicking the black arrow. If plans are unlocked then its associated TAB will be selected also.





Clicking Plan Explorer does:

- 1. Locate and select location(Room)
- 2. Locate and select planViewer drawing TAB if plans are Unlocked.



# PlanViewer

## Hyperlinks

Inter page links are possible to other pages within your planRoom registry. These may be either drawing files, regions within drawings or **pdf** page links.

Select the Hyperlink tool and then click on a position within the open drawing to place the link. The link will be placed as a shaded circle which may later be repositioned.





First select the type of link which will provide a filtered list of target files.



Drawing files allow optional selection of a region center within the drawing. The center point may be changed by clicking somewhere else or "right-clicking" to remove. Without a region point the whole drawing will later show. Click *Save* when done.



Selection handles will remain to allow positioning. Later the object may be selected or deleted as any other object. Modifying the link first requires selection of the circle to show selection handles followed by double clicking selection. Avoid clicking on the black jump arrow while to are trying to edit.

Once done, moving the mouse over the hyperlink will show the *Jump* arrow. Click the arrow and the pinViewer will appear if not yet showing and then load the linked drawing.





People Logic Software Corp. Phone: 250.475.1392 Fax: 250.475.0792 info@peoplelogicsoftware.com www.peoplelogicsoftware.com



Pdf links are done using the same Hyperlink tool. Change type to Pdf file and optionally select start page if different than page one. There is no preview.



Place Hyperlink. Note - The color of pdf links are different than those of drawings.





¢ ا	inViewer - 08210 - Wood Doors		
1	Save a Copy 🚔 🎽 🤗 🕅 See	rch 🕐 🚺 Select 🧱 🍳 • 🚺 💀 🛛 61% 🔹 🐵 🏥 🕲 :	∩• 🖹 🖊 sign •
yers			•
2		PART 2- PRODUCTS	
6		11 DITEROOR FLUIR WOOD DOORS:	
100		A Solid Cere Doors for Transporent Plank. Comply with the following requirement:	
		1. From Pinis Slowd Select White Miple Veneer from and build edges	
		2. Gender Pressent	
		3. Construction: PG-7 (Particleband core, 7-ply).	
		<ol> <li>Color: To month owner's complet.</li> </ol>	
		2.2 PREFITTING ADD PREPARATION FOR ILADINARE.	
		<ol> <li>Prefit and premachine wood doors at factory.</li> </ol>	
		C. Comply with twistness regressments of AWI pay spectrage. Metabase shorts he barrhome requiring compared doors. Comply with final hardwares schaldings and door frame slope dramatings and with hardwares resplayments and after excession information required to scarce project for doors on all tradements.	
		D. Toke accurate field measurements of latcheave motions in metal former to verify dimensions and stigmout before proceeding with machining in factory.	
1		<ol> <li>Meni Antapic: Perachine antapic and femal shell edges for horderne where required for pers of for-could door.</li> </ol>	
		PART 3 - EXECUTION	
		3.1 DOTALLATION	
		A. Condition doors to average provaling leanistry in incellation may prior to langing	
1		<ol> <li>Konferster. For mutallesian on Division-6 "Builders Hardware" section of these specifications.</li> </ol>	-
tients		C. Measdicture's instructions: Install wood does to comply with measdicture's instructions and of selenceed AWI stradent and as informed.	
diache		D handl far-and doors in corresponding far-anel frames in accordance with requirements of NFPA Na 82.	
5		E Profit Door: Fit to brazes and succluse for Audients to whether extend not previously worked at Sectory in required for Sit and customs cleanage it encl. edge.	
omments		<ol> <li>Usep-Fusionel Dance: Restrees fluids on edges on shap-fluidsed donts before scendarios, of frang read starchizarg is required or the job size.</li> </ol>	
2		North Cavalian Serings 00210-5	
			Contraction of the
12			
Dec	ument Drawing		



### **PinViewer**

The Pinviewer has been expanded to allow two concurrent images which automatically load from the left and shift to the right on each new image loaded.

The drawings may be originate from pin buttons *or* Hyperlinks. Each pane has its own zoom and pan controls.



Note – Delete only erases the view pane, not the source file.





## PlanRoom

Unlinked(not used) plans are designated in the outline with an "un-plugged" icon.



Note - Imported file names are now being scanned for illegal filenames symbols and "sanitized " prior to copying into planRoom.

## Fix Captions

Most captions names are derived from filenames if absent from source pdf files and this often results in confusing captions. To help in making these captions more readable a "Fix Caption" wizard now exists.

Example – Change all as New\_B110, New\_B112 ...





e	ect All I	JnSelect All Keep	Reset Us	e Filename
	Include	Original	<hr/>	New name
	~	00183745_original_B110	1	
	•	00183745_original_B112		
	~	00183745_original_8120		
	~	00183745_original_8124		
	•	00183745_original_B130		
	~	00183745_original_B132	Kee	ep "New name" as next
	~	00183745_original_B134	Or	iginal. Used if multiple
	~	00183745_original_B200	Remov	verAppend operation need
	-	00183745_original_B210		to be done
	~	00183745 original B220		
6	Bemov		Characters from	Begin 🗸
			Characters nom	Login III
	O Reillow		Characters @	
- (	Hemov	e Before	Character	7
1	Character (	count		
-	Character (	count		
I	Character (	count		
1	Character (	count cosition		
1	Character ( Character )	count		
	Character ( Character ) Character )	count		

#### 1. Remove Prefix.

#### 2. Add New\_

Scaption Fixer													
Select All UnSelect All Keep Reset Use Filename						Select All UnSelect All Keep Reset Use Filename							
ID	Include	e Original	New name	ID	Indu	ide Original				New name	1		
1	~	00183745_original_B110	B110	1	~	B110				New_B110			
2	~	00183745_original_B112	B112	2	~	B112				New_B112			
3	~	00183745_original_B120	B120	3	~	B120				New_B120			
4	00183745_original_B124 3		B124	4	~	B124				New_B124			
5	✓ 00183745_original_B130		B130	5	~	B130				New_B130			
6	~	00183745_original_B132	B132	6	~	B132				New_B132			
7	~	00183745_original_B134	B134	7	~	B134				New_B134			
8	~	00183745_original_8200	B200	8	~	B200				New_B200			
9		00183745_original_8210	B210	9	~	B210				New_B210			
10	~	00183745_original_8220	B220	10	~	B220				New_B220			
							1						
		Mass edit functio	ons 1				2	Mass	edit functi	ons			
Rem	ove App	bend	2	Rer	nove A	ppend							
Remove     I     Characters from     Begin     Characters from     Remove     Remove     Remove     Before     Character     Character     Character     Character     Character     Character     Character     Character					Add     Begin     G     Dinsett     Nov.     G     D     Replace     as     3  Text New								
Character position					Character position								
10/1	) Selecet	ed	Ok Cancel	10/	10 Selec	eted			4 —	Ok Cancel			



Done.

😑 NC Savings PlanRoom III
😑 Arch plans
Check Desk
Floor Plan
🖃 🔽 ID plans
🏷 ID604
😑 New sets
New_B110
New_B112
New_B120
<b>New_</b> B124
<b>New_B130</b>
New_B132
<b>New_</b> B134
New_B200
<b>New_B210</b>
<b>New_B220</b>
E Photos
Site Photo

## Reports

MODIFIED - Reports Lab\_sum and Lab\_sum3 labels for LaborType1/2 replaced with words Fabrication/Installation.

MODIFIED - Reports Mat\_sum and Mat\_sum3 labels for MaterialType1/2 replaced with as Fabrication/Buyout



## System

## Graphics

Share graphics such as product images may now be stored in a common folder called "Shared" in the path of your Data folder. This will allow reducing the individual project folder size by removing common baggage. In resolving the location of a graphic, takeoff will first search the project folder and then the Shared folder.



### Backups

Optional backup items show files size. Useful to avoid oversized backup files.





### **Missing Projects**

Projects where core files are missing are deemed as invalid projects and thus marked for deletion. Such projects are sent to Folder "DeletedProjects". Recylce bin also additionally for local projects.

Any comments are welcome for future enhancements.

Thank you for your ideas

People Logic Software

